



The 2nd Generation Intelli-Sense Charging System is physically longer than the previous version. Please follow these simple steps to replace your charging system.



A **Retrofit Mount Kit** is available for cart models without additional mounting holes.



Order Part #: 1324551

- 1) Determine if your cart is pre-drilled to accept a Version 2 Intelli-Sense Charging System by examining if additional holes are next to the mounting brackets. If there are no holes, order retrofit mount kit.



- 2) Remove lower baskets and unplug all Power Cords / Cables / GFCI Module from existing Intelli-Sense Charging System. Then unscrew the (4) mounting screws from existing system and save for step 5.

